**ELCA****QUALITY SYSTEMS & CALIBRATIONS PVT. LTD.**S. No. 232/2, Pune-Nasik Road, Opp. Rupee Co-op. Bank Ltd., Bhosari, Pune - 411 039.
Tel. : 91-20-2712 9194, 2712 5024 Fax : 2712 6430 E-Mail : qc@elcalabs.com Web : www.elcalabs.comElca
006CERTIFICATE NO.
CHEM. T. 298 & MECH T 299**TEST REPORT**

Page : 1 / 2

To, GULMOHAR ENTERPRISES. Sr.No.80/11,Plot No.1,Bhosari Alandi Road,Magzin Chowk,Charoli, Wadmukhwadi,Pune-412 105.	REPORT NO.	N/6523/P	DATE	01.03.2013
	YOUR CHALLAN NO.	-		
	YOUR CHALLAN DT.	09.02.2013		
	SAMPLE RECD. DATE	09.02.2013		

Material Description : Fait Job Sample, Without Oil

STANDARD SPECIFICATION - - -

Samples not drawn by Elca

The above sample has been tested and the results are as below :

SALT SPRAY TEST

TEST AT : PUNE

TEST METHOD ASTM B 117 : 2011

TEST DATE : 01.03.2013

S.N.	Parameter / Description	Actual Values	Specification Req.	Remark
1	Loading Date	09.02.2013	-	-
2	Unloading Date	01.03.2013	-	-
3	Protection/Coating	Not used	-	-
4	Temperature within Exposure Zone	34.6 to 35.4°C	-	-
5	Exposure Period	480hrs	-	-
6	Salt Solution	4.87 to 4.99%	-	-
7	Type of Salt	NaCl (AR grade)	-	-
8	Type of Water	Distilled water	-	-
9	Fog Collection Volume in ml/hr/80cm ²	1.3 to 1.8	-	-
10	Fog Collection Sp Gravity	1.027 to 1.034	-	-
11	Fog Collection pH	6.87 to 6.99	-	-
12	Method of Cleaning	Running water	-	-
13	<< Period in Hrs >>		-	<< Observation >>
14	24		-	No Rust Observed.
15	48		-	No Rust Observed.
16	72		-	No Rust Observed.
17	96		-	No Rust Observed.
18	120		-	No Rust Observed.
19	144		-	No Rust Observed.
20	168		-	No Rust Observed.
21	192		-	No Rust Observed.
22	216		-	No Rust Observed.
23	240		-	No Rust Observed.
24	264		-	No Rust Observed.
25	288		-	No Rust Observed.
26	312		-	No Rust Observed.
27	336		-	No Rust Observed.

Contd . . .



ELCA

QUALITY SYSTEMS & CALIBRATIONS PVT. LTD.

S. No. 232/2, Pune-Nasik Road, Opp. Rupee Co-op. Bank Ltd., Bhosari, Pune - 411 039.
Tel. : 91-20-2712 9194, 2712 5024 Fax : 2712 6430 E-Mail : qc@elcalabs.com Web : www.elcalabs.com



Elca
006

TEST REPORT

To, GULMOHAR ENTERPRISES. Sr.No.80/11,Plot No.1,Bhosari Alandi Road,Magziq Chowk,Charoli, Wadmukhwadi,Pune-412 105.	REPORT NO.	N/6523/P	DATE	01.03.2013
	YOUR CHALLAN NO.			
	YOUR CHALLAN DT.	09.02.2013		
	SAMPLE RECD. DATE	09.02.2013		

SALT SPRAY TEST

TEST METHOD ASTM B 117 : 2011

TEST AT : PUNE


TEST DATE : 01.03.2013

S.N.	Parameter / Description	Actual Values	Specification Req.	Remark
28	360		-	No Rust Observed.
29	384		-	No Rust Observed.
30	408		-	No Rust Observed.
31	432		-	No Rust Observed.
32	456		-	No Rust Observed.
33	480		-	No Rust Observed.


END OF REPORT

For ELCA QUALITY SYSTEMS & CALIBRATIONS PVT. LTD.


Checked By


Authorised Signatory
M.S.Phadke
Dy.Tech.Manager

Result after 480 hours - No rust observed.


Authorised Signatory
M. S. PHADAKE
DY. TECH. MANAGER



ELCA

QUALITY SYSTEMS & CALIBRATIONS PVT. LTD.

S. NO. 232 / 2, PUNE - NASIK ROAD, BHOSARI, PUNE - 411 039, INDIA.

TEL. : 91 (20) 271 2 91 94, 5024 FAX : 2712 6430 E-MAIL : qc@elcalabs.com WEB : www.elcalabs.com



LAB ACCREDITED BY NABL
CHEM.T / 298 & MECH.T / 299

PHYSICAL CHEMICAL & METALLURGICAL TESTING



ELCA

QUALITY SYSTEMS &
CALIBRATIONS PVT. LTD

**SALT SPRAY TEST
REPORT**

DATE: 01.03.2013

Customer: Reliable Packaging Solution.

Lab Number	N 6523	Test Method	ASTM B-117(11)
------------	---------------	-------------	-----------------------



(BEFORE TEST)



(AFTER TEST)

Result after 480 hours: - No rust observed.

M. S. Phadake

Authorized Signatory

M. S. PHADAKE
DY. TECH. MANAGER

AN ISO / IEC 17025 ACCREDITED LAB

REGISTERED OFFICE : PLOT NO. A 444, ROAD NO. 37, RAM NAGAR, WAGLE ESTATE, THANE - 400 604, INDIA.

TEL. : 91 (22) 2582 44 99, 20 47, 31 42, 2583 34 10 FAX : 2582 53 94 E-MAIL : info@elcalabs.com WEB : www.elcalabs.com

(Terms & Conditions Overleaf)